

Klip-Lok / Klip-Tite Dirt Retention

Technical Bulletin 1.1



Talk to **THE SMART ROOF PEOPLE**
Visit www.globalroofs.co.za or email
info@globalroofs.co.za



GLOBAL ROOFING SOLUTIONS

Brownbuilt | HH Robertson



Technical Bulletin 1:1: Dirt Retention

Photographs of two projects of equal age – both installed for about 4.5 years. It is noticeable that most of the dirt (black and brown marks) that accumulates on the roof is trapped at the bottom of the narrow flutes, and the bottom of the sides of the longitudinal pan stiffening ribs with minimal accumulation at the transverse pan stiffeners. The dirt accumulation thus follows the height of the upstand – 41mm at the narrow flute, 2mm at the longitudinal pan stiffeners and 0.5mm at the transverse pan stiffeners.

Klip-Lok



Klip-Tite



Isando Tel: +27 (0) 11 898 2900
Bloemfontein Tel: +27 (0) 51 432 3724
Cape Town Tel: +27 (0) 21 521 1900
Durban Tel: +27 (0) 31 538 0940
East London Tel: +27 (0) 43 731 1895

Nelspruit Tel: +27 (0) 13 492 0746
Mossel Bay Tel: +27 (0) 44 695 0014
Polokwane Tel: +27 (0) 51 293 0313
Port Elizabeth Tel: +27 (0) 41 486 1270
Rustenburg Tel: +27 (0) 14 596 6121

Upington Tel: +27 (0) 54 332 1656
Exports Tel: +27 (0) 11 898 2900
Botswana Tel: +267 (002) 310 5761
Ghana Tel: +27 (0) 11 898 2976
Lesotho Tel: +266 (002) 22 312 244

Mozambique Tel: +258 (002) 82 305 0506
Namibia Tel: +264 (002) 61 263 890
Zambia Tel: +260 (002) 21 225 1315
Zimbabwe Tel: +263 (002) 477 4699