

Klip-Lok / Klip-Tite Dirt Retention Technical Bulletin 1.1

ROOFING LIKE NO OTHER

Talk to **THE SMART ROOF PEOPLE**
www.globalroofs.co.za
marketing@globalroofs.co.za



Technical Bulletin 1:1: Dirt Retention

Photographs of two projects of equal age – both installed for about 4.5 years. It is noticeable that most of the dirt (black and brown marks) that accumulates on the roof is trapped at the bottom of the narrow flutes, and the bottom of the sides of the longitudinal pan stiffening ribs with minimal accumulation at the transverse pan stiffeners. The dirt accumulation thus follows the height of the upstand – 41mm at the narrow flute, 2mm at the longitudinal pan stiffeners and 0.5mm at the transverse pan stiffeners.

Klip-Lok



Klip-Tite



Please visit our website or contact GRS for standard flashing details

Isando
Cape Town
Durban
Port Elizabeth
East London

Tel: +27 (0) 11 898 2900
Tel: +27 (0) 21 521 1900
Tel: +27 (0) 31 538 0940
Tel: +27 (0) 43 731 1826
Tel: +27 (0) 43 731 1826

Bloemfontein
Nelspruit
Polokwane
Rustenburg
Upington

Tel: +27 (0) 51 432 3724
Tel: +27 (0) 13 492 0746/7
Tel: +27 (0) 15 293 0313
Tel: +27 (0) 14 596 6121
Tel: +27 (0) 54 332 1657

Exports
Botswana
Namibia

Tel: +27 (0) 11 898 2900
Tel: +267 (002) 310 5761/2
Tel: +264 (002) 61 263 890

